

John R. Kasich, Governor Mary Taylor, Lt. Governor Craig W. Butter, Director

November 10, 2014

Mr. Bruce Bailey Vice President of Technical Affairs quasar energy group 5575 Granger Road, Suite 320 Independence, OH 44131

Re: Biosolids Site Review

Dear Mr. Bailey:

Ohio EPA received an email request on November 7, 2014 from quasar energy group to include the following sites as part of the Ringler Energy, LLC biosolids management program:

Field ID	Ohio EPA Site No.	County	<u>Township</u>
MOQ-08-01	59-00097	Morrow	Westfield
MOQ-08-02	59-00098	Morrow	Peru
MOQ-08-03	59-00099	Morrow	Peru

These sites are owned and operated by Ohio EPA Site 59-00097 is located southwest of the intersection of Ashley-Westfield Road and Prospect Mount Vernon Road. Ohio EPA Sites 59-00098 and 59-00099 are located on Prospect Mount Vernon Road, approximately 1.0 mile west of Worthington-New Haven Road.

A review of these sites was conducted by Ohio EPA. Consideration was given to soil and landscape characteristics, isolation distances from residences, geology and ground water conditions and the proximity to waterways and wells.

The review indicated that portions of these sites contain hydrologic group D soils. Please refer to the precipitation prohibitions and restrictions for group D soils found in Ohio Administrative Code (OAC) 3745-40-08(B)(2).

These sites are authorized to be included as part of the Ringler Energy biosolids program. This authorization is subject to conditions contained in both the NPDES permit and OAC 3745-40. Conditions contained in the NPDES permit and OAC 3745-40 may differ. In such cases, the more restrictive conditions from either the NPDES permit or OAC 3745-40 shall govern.

Highlights of these conditions are as follows:

- 1. Biosolids shall not be applied in buffer zones.
- 2. In accordance with federal/state rules, biosolids may not be applied within 33 feet of surface waters of the state.
- 3. Biosolids application shall be timed to avoid periods of excessive wetness to help prevent runoff from a site.
- 4. Records for the application of biosolids on these sites shall be maintained in accordance with the requirements found in OAC 3745-40-09(C).

All biosolids beneficially used at these sites shall be injected beneath the surface of the ground or immediately incorporated into the soil.

If you have any questions, please contact me at (614) 644-2150 or via email at betsy vanwormer@epa.ohio.gov.

Sincerely,

Betsy P. L. VanWormer, P.E. Environmental Engineer II


Ohio EPA Division of Surface Water

Cc: Morrow County Health Department
Morrow County Soil and Water Conservation District
Westfield Township Trustees
Peru Township Trustees

Belsy P. R. Van Vanner

Ec:

Sam Mullins, quasar energy group Cassie Eblin, quasar energy group Isaac A. Robinson, III, Chief, Ohio EPA/CDO





Ohio EPA Division of Surface Water 50 West Town Street, Suite 700 Columbus, OH 43216 (614) 644-2150 Beneficial Use Site Authorization Ringler Energy, LLC

Ohio EPA Site 59-00097 Field ID: MOQ-08-01

Morrow County Westfield Township







Ohio EPA Division of Surface Water 50 West Town Street, Suite 700 Columbus, OH 43216 (614) 644-2150 Beneficial Use Site Authorization Ringler Energy, LLC

Ohio EPA Sites 59-00098 and 59-00099 Field IDs: MOQ-08-02 and MOQ-08-03

Morrow County Peru Township

